

Welcome to Paulson Training Programs, Inc. SimTech™ Virtual Lab Lessons



SimTech™ is the world's most advanced injection molding simulator you can use to practice machine setup, molded-part problem solving, and cycle reduction all on your computer. Increase the number of molding experts in your facility in a fraction of the time it takes with "on-the-job training" with this powerful, proprietary, physics and math based (not rule-based) simulator. SimTech comes with pre-defined lab lessons depicting different molding scenarios with four levels of difficulty with new labs released monthly. Or you can set up your own "molding scenarios" with FreeMold for your employees to solve, focusing on just the specific problem you want. SimTech will revolutionize the way you train your employees.

Copyright © 2020 Paulson Training Programs, Inc.
All Rights Reserved
Printed in USA

Intentionally left blank

Important Notice

Trade Secrets and Proprietary Notice: This software contains valuable trade secrets and proprietary information of Paulson Training Programs, Inc. No part of this software may be reproduced or transmitted in any form or by any means, electronic, mechanical or otherwise without written permission from Paulson Training Programs, Inc.

SimTech is a trademark of Paulson Training Programs, Inc. other brand and product names are trademarks or registered trademarks of their respective holders.

Intentionally left blank

What is SimTech™?

SimTech™ is an Injection molding machine simulator (think Flight simulator for Injection Molding). It is based on physics and mathematics – ***not*** ruled-based and can perform over 26 million calculations. SimTech is designed to be used after an interactive training module has been taken to allow a student to apply what they have learned furthering their understanding of the subject matter.

What are some of the Key Features & Benefits of SimTech?

- Runs a cycle in a 1-2 seconds
- 22 fully functioning molding machine controls, including Velocity-to-Pressure transfer (VPT)
- Reports 8 of the most common part problems from molding conditions
- Provides students with “at-the-machine” skills training without:
 - Wasting machine time
 - Wasting plastic
 - Risking damaging the machine or mold
- Interactive
- Units can be either US (English) or SI (Metric)
- Turns learning into a challenging “game”

How is SimTech different than Skillbuilder?

Skillbuilder is a simplified version of SimTech. Pre-programmed lessons lead the student on a specific path to address a pre-defined problem. Skillbuilder serves as the introduction to the use of SimTech.

SimTech allows a student to use their molding knowledge to improve machine set-ups and solve problems by making machine control changes, cycling the machine, and then analyzing the Cycle Results. Paulson provides lab lessons with predefined setups that require molded part problems to be solved along with cycle optimization. With SimTech, managers can also set up their own problem scenarios for the employees to solve.

What is the difference between SimTech “FreeMold” and SimTech Lab lessons?

Both run through SimTech. Lab Lessons are pre-defined lessons that Paulson has created which are assigned to personnel to target specific areas of learning.

“Freemold” operation lets ***you*** decide your own set-up by choosing your machine size, plastic, mold and dimensional tolerance from the Simtech database. You can set up scenarios for your employees or peers to solve specific molding problems, or just optimize a cycle.

How are my lab lessons scored?

Each lab lesson description states what must be accomplished in order to complete a lesson.



SimTech™

How to Use this Manual

The SimTech™ Lab Lessons are designed to be used in conjunction with the interactive training courses. After you have taken The Technology of Injection Molding Levels 1 & 2, and the Injection Molding Problems and Solutions course (along with the Skillbuilder lessons that accompany them), you will be ready to take the SimTech Lab Lessons. Now you can really apply what you have learned!

The manual is split up into sections.

- 1. How to Use this Manual** – Instructions on how to use the SimTech manual.
- 2. Training Administrator Instructions** – How to sign students up for SimTech lab lessons.
- 3. Tutorial Answer Key** – All the answers to the Student Workbook Tutorial for the training administrator.
- 4. Student Tutorial Workbook – Getting Started** – How to begin the Student Tutorial.
- 5. Student Tutorial Workbook** - Familiarizes the student with how to use SimTech. If a student is already familiar with SimTech, they can skip right to the Lab Lessons.
- 6. Student Tutorial Workbook - Answer Sheet** – Can be used to make copies for each student in order to write their answers for the Student Workbook Tutorial exercise.
- 7. Lab lessons – Getting Started** – How to log into the SimTech Lab lessons.
- 8. Lab lessons** – Scenarios/problems developed by Paulson Training that the students must solve while meeting certain criteria. A student will need a copy of each Lab Lesson they are to take.
 - 4 Levels of difficulty
 - Levels 1 (easiest) – 4 (hardest)

***All sections of this manual can be downloaded from our website at:**

www.paulsontraining.com/support-center

Intentionally Left Blank



SimTech™

Training Administrator Instructions

Assigning users to SimTech is very similar to assigning users to Skillbuilder.

1. Go to www.paulsonskillbuilder.com and login using your provided credentials.

Login


E-mail:

Password:


Remember me (for 30 days)

Login

2. Next you'll be at the home page of the Manager. Click on 'Manager Home'.




- As the Manager for your company’s employees, you can add new students, assign SimTech lab lessons and FreeMold to their accounts, and do various other Manager functions.



- To Add a New Student

Click the ‘Add a New Student’ button. Fill in the required fields. Please note the email address does not have to be a valid email address, recognizing that not all employees have a company email, but it must follow email conventions. Example: tjones@abcco.com



5. Adding Employees to SimTech or SkillBuilder as a Group

To enroll multiple employees into SimTech or SkillBuilder, create a *.csv file with their information and import using the Import 'New Students From CSV' button.



Below is a sample .csv file. At your request we can email you a blank *.csv file as a template. For each employee, you will need to provide an email address, first name, last name, and a password. Each employee can change their password anytime they login.

NOTE: The email address does **not** have to be a valid email, recognizing that not all employees have a company email. It just needs to follow email conventions, namely an “@”. No email will be sent to that address, it is only used for login purposes. Passwords must be a minimum of six characters.

	A	B	C	D	E
1	auth_user.email	auth_user.first_name	auth_user.last_name	auth_user.password	
2	email1@email.com	firstname	lastname	123456	
3	email2@email.com	firstname	lastname	234567	
4	email3@email.com	firstname	lastname	345678	
5					
6					
7					



This button assigns all the SimTech lab lessons you have purchased, to your employees. So after you have imported all your employees via a *.csv file, click this button to assign them SimTech lab lessons. From this point, all your employees will have access to all their SimTech lab lessons.

6. Student Reports

From the Manager Home page, click on 'Student Reports'. There are four different reports available. Each report indicates if a lesson is assigned, finished, percent complete, and date last accessed.

Comprehensive Student Report – Lists all students

Assigned Lesson Report - Lessons currently assigned to the student

Former Lessons Report - Lessons previously assigned to the student that are no longer assigned

All Lessons Report - Lessons currently assigned and previously assigned

The screenshot shows a web browser window displaying the Paulson Training Programs, Inc. interface. The page title is "Student Reports for <Trial Account 2> Organization". There are two buttons at the top: "Back" and "Comprehensive Student Report". Below the buttons, it says "12 records found". The main content is a table with the following columns: E-mail, First name, Last name, Assigned Lessons Report, Former Lessons Report, and All Lessons Report. The table contains 12 rows of data.

E-mail	First name	Last name	Assigned Lessons Report	Former Lessons Report	All Lessons Report
cpaulson1@paulsontraining.com	Craig	Paulson	Assigned Lessons Report	Former Lessons Report	All Lessons Report
dan.ralph@hennepin.edu	Dan	Ralph	Assigned Lessons Report	Former Lessons Report	All Lessons Report
jasonchen@moldex3d.com	Jason	Chen	Assigned Lessons Report	Former Lessons Report	All Lessons Report
joeylabitag@gmail.com	Joey	Labitag	Assigned Lessons Report	Former Lessons Report	All Lessons Report
jrjce@tool-n-die.com	Jeff	Rice	Assigned Lessons Report	Former Lessons Report	All Lessons Report
lbudz@blackhawkmolding.com	Lenn	Budz	Assigned Lessons Report	Former Lessons Report	All Lessons Report
loren@ron-vik.com	Loren	Pribyl	Assigned Lessons Report	Former Lessons Report	All Lessons Report
naveedakramuet@hotmail.com	Naveed	Akram	Assigned Lessons Report	Former Lessons Report	All Lessons Report
ogarcia@rainbird.com	Omar	Garcia	Assigned Lessons Report	Former Lessons Report	All Lessons Report
test@test.com	Test	test	Assigned Lessons Report	Former Lessons Report	All Lessons Report
trialaccount2@gmail.com	Jennifer	Lentz	Assigned Lessons Report	Former Lessons Report	All Lessons Report
vincent@evergreenplastic.com	Vincent	Do	Assigned Lessons Report	Former Lessons Report	All Lessons Report



SimTech™

Tutorial Answer Key

(for Training Administrator)

This answer key provides all the answers to the Student Workbook Tutorial. The Student Workbook Tutorial should be taken by all users who are not familiar with how SimTech™ works. If a user is already familiar with SimTech™ and how it operates, they can move directly to the SimTech™ lab lessons located at the end of this manual.

The Student Workbook Tutorial is designed to show a user how to navigate through the SimTech™ control panel and the effects of each molding machine control on the plastic behavior and on the molded part properties. Users will be directed to make specific control changes and then asked to record and explain the results. Provided in the Student section of this manual, is a Student Answer Sheet which you can make copies of for students to write their answers in.

By the end of this tutorial, the user should be familiar with how to:

- Make machine control changes
- Cycle the machine
- Read the cycle results
- Identify part problem
- Identify machine alarms
- Will have observed the effects of each control and each alarm

The Student Tutorial Lesson is taken through FreeMold which allows a user to pick their machine size, plastic and part. This tutorial lesson uses a 300 ton machine, molding the “cover” using Polystyrene. After completing this tutorial, a user can change the type of machine, plastic, or part using the **New Session** button and do a similar evaluation for this new setup.

Note: All pressures shown on the SimTech™ control panel are plastic pressures, not hydraulic oil pressures.

Intentionally left blank

SimTech™ Tutorial – Answer Key

I. Effects of Barrel Temperature on Melt Temperature

A. You will now determine the effect on the melt temperature of each of the barrel zone temperatures.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	450	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	35	Pressures/Time		
Screw Back Pressure	psi	500	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300	Part Problems (most recent cycle to the left)		
<input type="button" value="Cycle"/> <input type="button" value="History"/> <input type="button" value="Edit Setup"/> <input type="button" value="Change Units"/> <input type="button" value="User Sessions Page"/>			Flash		
Cycle Graphs			Burn Mark		
			Size (+/- 0.01 in)		
			Weld Lines		
			Short Shot		
			Warp		
			Sink Marks		
			Voids		
			Machine Alarms		
			Screw Recovery	<input checked="" type="checkbox"/>	
			Max Pressure	<input checked="" type="checkbox"/>	
			No Cushion	<input checked="" type="checkbox"/>	
			Low Melt	<input checked="" type="checkbox"/>	
			High Melt	<input checked="" type="checkbox"/>	

What is the melt temperature? ? 445.7 °F

II. Determine the Effect of Each Barrel Zone Temperatures on the Melt Temperature

A. You will raise each barrel zone by 20°F to determine which zone has the greatest effect.

1. Raise rear zone barrel temperature to 470°F. [Cycle the machine]

What is the melt temperature? 447.0 °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	470	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	500	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70		s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	447.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.90
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.37

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

- Raise the middle zone temperature to 470°F and set the rear zone temperature back to 450°F. [Cycle the machine]

What is the melt temperature? 448.7 °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	450	Fill Rate 1	in/s	2
Middle Zone Temp	F	470	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	35	Pressures/Time		
Screw Back Pressure	psi	500	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

Name	Units	Value
Melt Temp	F	448.7
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	8.38

Flash
Burn Mark
Size (+/- 0.01 in)
Weld Lines
Short Shot
Warp
Sink Marks
Voids

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Pressure (psi)

Screw Travel (in)

Injection Pressure

- Raise the front zone barrel temperature and nozzle temperature to 470°F and set the middle zone back to 450°F. [Cycle the machine]

What is the melt temperature? 458.5 °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	450
Middle Zone Temp	F	450
Front Zone Temp	F	470
Nozzle Temp	F	470
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	500
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	458.5
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.87
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.47

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Which zone affected the melt temperature the most? Front

Why? Plastic in the metering section is a thin layer. Therefore, it is heated faster by the barre heaters than the other zones. If the front zone temperature was lower than the melt temperature, the plastic would be cooled by the front zone.

4. Typical barrel zone settings for this plastic are: 450°F nozzle, 450°F front, 450°F middle, 400°F rear. Set the zones to these settings. [Cycle the machine]

What is the melt temperature? 441.7 °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	500
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	441.7
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT %	%	94.91
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.32

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Cycle Graphs

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History Edit Setup Change Units User Sessions Page

III. Determine the Effect of the Back Pressure on the Melt Temperature

A. Increased back pressure causes more heating of the plastic in the barrel.

1. Raise the back pressure and repeat the cycle until melt temperature is the same as the front zone temperature. (i.e. 450°F)

What is the back pressure when the melt temperature is 450°F? 1,955 psi

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	1955
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	12.97

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

Explain why the melt temperature increased when the back pressure was increased.

Increased back pressure requires more energy to move plastic heat is generated through the shearing action.

Why is it best to have the front zone temperature and the melt temperature the same?

So the plastic is neither heated nor cooled while it waits for injection.

IV. Effects of Screw Back Setting

A. The screw back setting determines how far back the screw returns when it rotates. Screw back setting also controls the cushion size.

1. Set the screw back distance to 3.5” and the VPT setpoint to 1.35”. [Cycle]

What is the present cushion size? 1.251 in

Is the cushion size all Right? No

Explain: The plastic ahead of the screw is being heated too long by having a large cushion.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	1955
Screw Back Distance	in	3.5
VPT Setpoint	in	1.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	450.2
Fill Time	s	1.09
Cycle Time	s	37.09
Mold Full at VPT	%	95.77
Cushion Size	in	1.251
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	13.04

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

Cycle History: [Cycle](#) | [History](#) | [Edit Setup](#) | [Change Units](#) | [User Sessions Page](#)

2. Reduce the screw back setting to 2.0” and the VPT setpoint to 0.4”. [Cycle]

What happened? No cushion alarm came on.

Why? There was not enough plastic ahead of the screw when injection occurred

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	35	Pressures/Time		
Screw Back Pressure	psi	1955	Max Injection Pressure	psi	25000
Screw Back Distance	in	2	Ramp Time	s	0
VPT Setpoint	in	0.4	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.8
Fill Time	s	0.83
Cycle Time	s	36.83
Mold Full at VPT %	%	71.61
Cushion Size	in	0.000
Part Length	in	6.269
Part Weight	oz	3.128
Screw Run Time	s	11.48

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	■
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

3. Set the screw back position so that the cushion size is between 0.125” and 0.250” [Cycle].

Note: In the ProMolder Series we consider an optimized cushion to be in a range of 5-10% of the total shot size.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results																		
Name	Units	Value	Name	Units	Value																
Barrel Temperatures			Fill Rates																		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2																
Middle Zone Temp	F	450	Fill Rate 2	in/s	2																
Front Zone Temp	F	450	Fill Rate 3	in/s	2																
Nozzle Temp	F	450	Fill Rate 4	in/s	2																
Injection Unit			Fill Rate 5	in/s	2																
Screw Rotation	rpm	35	Pressures/Time																		
Screw Back Pressure	psi	1955	Max Injection Pressure	psi	25000																
Screw Back Distance	in	2.48	Ramp Time	s	0																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500																
Mold and Clamp			Pack/Hold Time	s	5																
Mold Moveable Temp	F	70	Cooling Time	s	30																
Mold Stationary Temp	F	70	Mold Open Time	s	1																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																		
<div style="display: flex; justify-content: space-between;"> Cycle History Edit Setup Change Units User Sessions Page </div>			<table border="1"> <tr><td>Flash</td><td></td></tr> <tr><td>Burn Mark</td><td></td></tr> <tr><td>Size (+/- 0.01 in)</td><td style="text-align: center;">■</td></tr> <tr><td>Weld Lines</td><td></td></tr> <tr><td>Short Shot</td><td style="text-align: center;">■</td></tr> <tr><td>Warp</td><td></td></tr> <tr><td>Sink Marks</td><td></td></tr> <tr><td>Voids</td><td></td></tr> </table>			Flash		Burn Mark		Size (+/- 0.01 in)	■	Weld Lines		Short Shot	■	Warp		Sink Marks		Voids	
Flash																					
Burn Mark																					
Size (+/- 0.01 in)	■																				
Weld Lines																					
Short Shot	■																				
Warp																					
Sink Marks																					
Voids																					
Cycle Graphs			Machine Alarms																		
			<table border="1"> <tr><td>Screw Recovery</td><td style="text-align: center;">●</td></tr> <tr><td>Max Pressure</td><td style="text-align: center;">●</td></tr> <tr><td>No Cushion</td><td style="text-align: center;">●</td></tr> <tr><td>Low Melt</td><td style="text-align: center;">●</td></tr> <tr><td>High Melt</td><td style="text-align: center;">●</td></tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●						
Screw Recovery	●																				
Max Pressure	●																				
No Cushion	●																				
Low Melt	●																				
High Melt	●																				

What is the screw back position you have set? The screw back distance should be set around 2.48 in.

What is the VPT setpoint you have set? The VPT setpoint should be 0.35 in. This gives us a 94 – 96% range.

What is the melt temperature? 450.0 °F

Note: Do not re-adjust back pressure yet.

V. Determine the Effect of Screw RPM on the Melt Temperature

A. Screw rpm can also affect the plastic temperature, but the magnitude of the affect depends on the screw design and the amount of non-Newtonian viscosity change that occurs.

1. Increase screw rpm to 150. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	150
Screw Back Pressure	psi	1955
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	453.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.88
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	2.42

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What is the melt temperature? 453.0 °F

Why did the melt temperature increase? Higher screw rpm requires more energy. Most of the energy is converted to heat in the plastic.

2. Adjust the back pressure so that the melt temperature is 450°F. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	■
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History Edit Setup Change Units User Sessions Page

Cycle Graphs

What is the back pressure to achieve 450°F melt temperature? 1,335 psi

VI. Maximum Injection Pressure Alarm

A. The Maximum Injection Pressure Alarm will activate if the machine has tried to exceed its maximum injection pressure.

1. Reduce max injection pressure to 1,100 psi. and reduce the Pack/Hold pressure to 1,000 psi [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	1100
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1000
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	0.00
Cycle Time	s	36.00
Mold Full at VPT	%	94.75
Cushion Size	in	0.330
Part Length	in	6.419
Part Weight	oz	3.170
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash		
Burn Mark		
Size (+/- 0.01 in)	■	■
Weld Lines		
Short Shot	■	■
Warp		
Sink Marks		
Voids		

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Pressure (psi)

2k
1k
0k

0 0.2 0.4 0.6 0.8 1 1.2 1.4 1.6 1.8 2 2.2 2.4

Screw Travel (in)

◆ Injection Pressure

Why did the Low Max Injection Pressure alarm occur? Injection pressure during mold filling is not enough to maintain the set fill rate.

2. Raise the max injection pressure to 10,000 psi and the Pack/Hold pressure to 1,700 psi. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.66

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

Problem	Indicator
Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	■
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

VII. The Screw Recovery Alarm

A. The Screw Recovery alarm will activate if the screw does not rotate fast enough thus, enabling the screw to return to the Screw Back Distance setting before the next shot.

1. Lower the screw speed to 13 rpm. **[Cycle]**

What alarm occurred? Screw Recovery Alarm.

Why? The screw did not have time to return before the mold opened

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	13
Screw Back Pressure	psi	1335
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	10000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	448.1
Fill Time	s	1.05
Cycle Time	s	37.05
Mold Full at VPT %	%	76.94
Cushion Size	in	0.000
Part Length	in	6.270
Part Weight	oz	3.121
Screw Run Time	s	30.00

Part Problems (most recent cycle to the left)

Problem	1	2	3
Flash			
Burn Mark			
Size (+/- 0.01 in)			
Weld Lines			
Short Shot			
Warp			
Sink Marks			
Voids			

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Cycle History: Cycle History Edit Setup Change Units User Sessions Page

2. Raise rpm to 150. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.66

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	1335	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	30
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.19
Cycle Time	s	37.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.132
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash				
Burn Mark				
Size (+/- 0.01 in)	■	■	■	■
Weld Lines	■	■	■	■
Short Shot	■	■	■	■
Warp				
Sink Marks				
Voids				

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

What is the melt temperature? 450.0 °F

VIII. Determine the Effect of the Mold Closed Time on the Melt Temperature

A. You will explore how the mold closed timer can affect the melt temperature.

1. Reduce mold closed time to 15 seconds. [Cycle]

(the cooling time is the same thing as the mold closed time)

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	1335	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	15
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	442.9
Fill Time	s	1.22
Cycle Time	s	22.22
Mold Full at VPT	%	94.91
Cushion Size	in	0.231
Part Length	in	6.507
Part Weight	oz	3.134
Screw Run Time	s	2.11

Part Problems (most recent cycle to the left)

Flash				
Burn Mark				
Size (+/- 0.01 in)	■	■	■	■
Weld Lines	■	■	■	■
Short Shot	■	■	■	■
Warp				
Sink Marks				
Voids				

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Pressure (psi) vs Screw Travel (in)

Legend: Injection Pressure

What is melt temperature? 442.9 °F

Why did the melt temperature decrease? There is now less time for the plastic to be heated by the barrel

2. Use the back pressure to raise the melt temperature to 450°F ±2°. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	2325	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.19
Cycle Time	s	22.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.57

Part Problems (most recent cycle to the left)

Flash									
Burn Mark									
Size (+/- 0.01 in)									
Weld Lines									
Short Shot									
Warp									
Sink Marks									
Voids									

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the new back pressure setting? 2,325 psi

IX. The Back Pressure and No Cushion Alarms

A. Why the back pressure and no cushion alarms come on

1. Raise back pressure to 6000 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	6000	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	473.3
Fill Time	s	0.25
Cycle Time	s	21.25
Mold Full at VPT	%	7.76
Cushion Size	in	0.000
Part Length	in	2.915
Part Weight	oz	3.090
Screw Run Time	s	2.39

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■ ■ ■
Weld Lines	■ ■ ■
Short Shot	■ ■ ■
Warp	
Sink Marks	
Voids	■ ■ ■

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What alarms occurred? No cushion alarm and high melt alarm

Why? The screw could not return against the high back pressure. When the mold opened the screw is required to stop rotating. There was not enough plastic ahead of the screw for the next shot.

2. Reset the back pressure to 2,325 psi. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	2325	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70		s	15
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.19
Cycle Time	s	22.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.57

Part Problems (most recent cycle to the left)

Flash									
Burn Mark									
Size (+/- 0.01 in)									
Weld Lines									
Short Shot									
Warp									
Sink Marks									
Voids									

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

X. Determine the Effect of Mold Open Time on the Melt Temperature

A. You will explore how the mold open timer can affect the melt temperature.

1. Increase the mold open time to 5 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	2325	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	5
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	452.0
Fill Time	s	1.19
Cycle Time	s	26.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.59

Part Problems (most recent cycle to the left)

Problem	1	2	3	4	5	6	7	8	9	10
Flash										
Burn Mark										
Size (+/- 0.01 in)										
Weld Lines										
Short Shot										
Warp										
Sink Marks										
Voids										

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the melt temperature? 452.0 °F

Why did the temperature increase? With an increased mold open time the plastic has more time to be heated in the barrel.

2. Set the mold open time to 1 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	150
Screw Back Pressure	psi	2325
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.19
Cycle Time	s	22.19
Mold Full at VPT %		94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.57

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	10000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Cycle | **History** | **Edit Setup** | **Change Units** | **User Sessions Page**

Cycle Graphs

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

XI. Determine the Effect of the Mold Temperature on the Melt Temperature

A. You will explore how the mold temperature can affect the melt temperature.

1. Set mold temperature to 110°F (both halves). [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	2325	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	110	Cooling Time	s	15
Mold Stationary Temp	F	110	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.15
Cycle Time	s	22.15
Mold Full at VPT	%	94.86
Cushion Size	in	0.231
Part Length	in	6.505
Part Weight	oz	3.127
Screw Run Time	s	2.57

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	■
Sink Marks	
Voids	■

Machine Alarms

- Screw Recovery: ●
- Max Pressure: ●
- No Cushion: ●
- Low Melt: ●
- High Melt: ●

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

Cycle Graphs

What is the melt temperature? 449.6 °F

Does the mold temperature affect the melt temperature in the barrel? No

XII. Determine the Effects of Fill Rates on the Molded Parts

A. You will explore how fill rates can affect the molded parts.

1. Set barrel rear zone to 380°F, middle zone to 385°F, front and nozzle to 400°F. [Cycle]
2. Set screw rotation to 65 rpm and screw back pressure to 600 psi. [Cycle]
3. Set mold temperature to 60°F (both halves). [Cycle]
4. Set all fill rates 4.0 in/sec. [Cycle]
5. Set the max injection pressure to 25,000 psi. [Cycle]

Note: This molding machine has a maximum fill rate of 25 inches per second.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 138.79

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	4
Fill Rate 2	in/s	4
Fill Rate 3	in/s	4
Fill Rate 4	in/s	4
Fill Rate 5	in/s	4
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.62
Cycle Time	s	21.62
Mold Full at VPT	%	94.88
Cushion Size	in	0.230
Part Length	in	6.503
Part Weight	oz	3.117
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	█
Weld Lines	█
Short Shot	█
Warp	█
Sink Marks	
Voids	█

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Cycle History: Cycle History Edit Setup Change Units User Sessions Page

What is the fill time? 0.62 sec

What is the cycle time? 21.62 sec

What is the part weight? 3.117 oz.

What is the part length? 6.503 in

6. Set Fill Rates 1, 2, 3, and 4 to 10.0 in/sec.

7. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 140.75

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	10
Middle Zone Temp	F	385	Fill Rate 2	in/s	10
Front Zone Temp	F	400	Fill Rate 3	in/s	10
Nozzle Temp	F	400	Fill Rate 4	in/s	10
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.32
Cycle Time	s	21.32
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.501
Part Weight	oz	3.109
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	■
Sink Marks	
Voids	■

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the fill time? 0.32 sec

What is the cycle time? 21.32 sec

What is the part weight? 3.109 oz.

What is the part length? 6.501 in

What changes occurred to the molded parts? Part weight decreased very slightly, dimensionally there is a very slight change but no significant change is observed.

8. Set Fill Rates 1, 2, 3, and 4 to 3.0 in/sec.

9. Set Fill Rate 5 to 6.0 in/sec. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.72
Cycle Time	s	21.72
Mold Full at VPT	%	95.99
Cushion Size	in	0.230
Part Length	in	6.503
Part Weight	oz	3.118
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	■
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	■
Sink Marks	
Voids	■

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Fill Rates

Name	Units	Value
Fill Rate 1	in/s	3
Fill Rate 2	in/s	3
Fill Rate 3	in/s	3
Fill Rate 4	in/s	3
Fill Rate 5	in/s	6

Pressures/Time

Name	Units	Value
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Cycle Graphs

The graph shows Injection Pressure (psi) on the y-axis (0k to 3k) and Screw Travel (in) on the x-axis (0 to 2.4). The pressure curve starts at 0, rises sharply to a peak of about 2.5k psi at 0.2 in, then drops to around 2k psi and continues to decrease in steps as screw travel increases, reaching approximately 0.5k psi at 2.4 in.

What is the fill time? 0.72 sec

What is the cycle time? 21.72 sec

What is the part weight? 3.118 oz.

What is the part length? 6.503 in

What happened to part weight and dimensions when the final Fill Rate 5 is very fast?

The part weight and dimensions increased. Burn marks are also present

Why? The machine uses higher pressures to fill at higher flow rates so more plastic is packed into cavities.

10. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec.

11. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.24

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.24
Cycle Time	s	21.24
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.500
Part Weight	oz	3.106
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Problem	Severity
Flash	None
Burn Mark	Low
Size (+/- 0.01 in)	High
Weld Lines	High
Short Shot	High
Warp	Low
Sink Marks	None
Voids	High

Machine Alarms

- Screw Recovery: ●
- Max Pressure: ●
- No Cushion: ●
- Low Melt: ●
- High Melt: ●

Cycle Graphs

What is the fill time? 0.24 sec

What is the cycle time? 21.24 sec

What is the part weight? 3.106 oz.

What is the part length? 6.500 in

What happened to part weight and dimensions when final Fill Rate 5 is reduced? The part weight and dimensions decrease.

Why? The plastic cools while it is flowing. The gate begins to freeze and a thicker skin of frozen material forms causing a decrease in volumetric flow. The result is decreased dimensions and part weight.

Fill Rates Conclusions:

- Very high fill rates require high injection pressures.
- Of all the fill rates, the final Fill Rate 5 has the greatest effect on part dimensions and weight.

2. Reduce clamp force to 65 tons. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	65

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	4
Fill Rate 2	in/s	4
Fill Rate 3	in/s	4
Fill Rate 4	in/s	4
Fill Rate 5	in/s	8
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.53
Cycle Time	s	21.53
Mold Full at VPT %	%	96.27
Cushion Size	in	0.230
Part Length	in	6.502
Part Weight	oz	3.113
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	<input checked="" type="checkbox"/>
Burn Mark	<input type="checkbox"/>
Size (+/- 0.01 in)	<input type="checkbox"/>
Weld Lines	<input type="checkbox"/>
Short Shot	<input type="checkbox"/>
Warp	<input type="checkbox"/>
Sink Marks	<input type="checkbox"/>
Voids	<input type="checkbox"/>

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What change occurred in the defects present? The burn marks were eliminated, but the part now has flash.

Why? More air could escape at the lower clamp force, but the lower clamp force allowed flash.

3. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

4. Set the Clamp Force to 75 tons. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.24

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	75	Part Problems (most recent cycle to the left)		

Flash Burn Mark Size (+/- 0.01 in) Weld Lines Short Shot Warp Sink Marks Voids

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle History Edit Setup Change Units User Sessions Page

Cycle Graphs

What happened to the flash? Flash was eliminated.

Why? The slower fill rate at the end of fill reduced the cavity pressure enough so that the mold no longer flashed.

What conclusions would you make concerning the effects of clamp force and fill rate on burn marks and flash? The final fill rate affects both burns and flash. The amount of clamp force affects burns and flash.

XIV. Determine the Effects of Pack/Hold pressure on the Molded Part Properties

A. Now we'll examine the effect of pack/hold pressure on part weight and dimensions.

1. Increase the clamp force to 300 tons. (This will avoid flash when we increase the pack/hold pressure.) [Cycle]
2. Increase the pack/hold pressure to 5,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.46

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 21.21 sec

What is the part weight? 3.148 oz.

What is the part length? 6.510 in

Why did the part size increase? The higher holding pressure packed more plastic in the cavity.

3. Reduce the pack/hold pressure to 4,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.45

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	4500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.507
Part Weight	oz	3.135
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 21.21 sec

What is the part weight? 3.135 oz.

What is the part length? 6.507 in

Why did the part dimensions and weight decrease when the pack/hold pressure was reduced?
The lower Pack/Hold pressure puts plastic molecules into the cavity.

4. Raise the pack/hold pressure to 6,000 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	6000
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.511
Part Weight	oz	3.155
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 21.21 sec

What is the part weight? 3.155 oz.

What is the part length? 6.511 in

Notice the part dimensions are now out of spec. Why did this happen? The higher Pack/Hold Pressure pushes more plastic molecules into the mold. This increases the part weight and reduces the overall shrinkage. In this case so much so that the part is too large.

5. Decrease the pack/hold pressure to 2,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.40

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	2500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	<input type="radio"/>
Max Pressure	<input type="radio"/>
No Cushion	<input type="radio"/>
Low Melt	<input type="radio"/>
High Melt	<input type="radio"/>

What is the fill time? 0.22 sec

What is the cycle time? 21.22 sec

What is the part weight? 3.113 oz.

What is the part length? 6.502 in

XV. Determine the Effects of Pack/Hold Time on the Molded Part Properties

A. Now we'll examine the effect of pack/hold time on part weight and dimensions.

Note: Too short a holding time can cause “discharge”.

1. Set the Pack/Hold Pressure back to 5,500 psi. [Cycle]

- You should have a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.46

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	<input type="checkbox"/>
Burn Mark	<input type="checkbox"/>
Size (+/- 0.01 in)	<input checked="" type="checkbox"/>
Weld Lines	<input type="checkbox"/>
Short Shot	<input type="checkbox"/>
Warp	<input type="checkbox"/>
Sink Marks	<input type="checkbox"/>
Voids	<input type="checkbox"/>

Machine Alarms

Screw Recovery	<input type="checkbox"/>
Max Pressure	<input type="checkbox"/>
No Cushion	<input type="checkbox"/>
Low Melt	<input type="checkbox"/>
High Melt	<input type="checkbox"/>

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 21.21 sec

What is the part weight? 3.148 oz.

What is the part length? 6.510 in

Is there any change in the molded parts? The part is now within specification although it is to the upper specification limit.

2. Set pack/hold time to 3 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 156.19

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	3
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	399.2
Fill Time	s	0.21
Cycle Time	s	19.21
Mold Full at VPT	%	95.21
Cushion Size	in	0.231
Part Length	in	6.509
Part Weight	oz	3.146
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	<input type="checkbox"/>
Burn Mark	<input type="checkbox"/>
Size (+/- 0.01 in)	<input checked="" type="checkbox"/>
Weld Lines	<input type="checkbox"/>
Short Shot	<input type="checkbox"/>
Warp	<input type="checkbox"/>
Sink Marks	<input type="checkbox"/>
Voids	<input type="checkbox"/>

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 19.21 sec

What is the part weight? 3.146 oz.

What is the part length? 6.509 in

Is there any change in the molded parts? There is a very slight decrease in part weight and part length.

3. Set holding time to 1 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 174.34

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	1
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

Name	Units	Value
Melt Temp	F	398.1
Fill Time	s	0.21
Cycle Time	s	17.21
Mold Full at VPT	%	95.21
Cushion Size	in	0.231
Part Length	in	6.509
Part Weight	oz	3.144
Screw Run Time	s	4.32

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the fill time? 0.21 sec

What is the cycle time? 17.21 sec

What is the part weight? 3.144 oz.

What is the part length? 6.509 in

Is there any change in the molded parts? There is a very slight decrease in part weight and part length.

XVI. Find the Gate Freeze Time

1. Set the Pack/Hold Time to 0.1 second. **[Cycle]**
2. Continue to increase the Pack/Hold Time by 0.1 seconds until you find that the part weight and length does not change.
 - Once the part weight and part length do not change that means the gate has frozen.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 172.33

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	1.2
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300	Part Problems (most recent cycle to the left)		
<div style="display: flex; justify-content: space-between;"> Cycle History Edit Setup Change Units User Sessions Page </div>			Flash Burn Mark Size (+/- 0.01 in) Weld Lines Short Shot Warp Sink Marks Voids		
Cycle Graphs			Machine Alarms		
			Screw Recovery <input type="checkbox"/> Max Pressure <input type="checkbox"/> No Cushion <input type="checkbox"/> Low Melt <input type="checkbox"/> High Melt <input type="checkbox"/>		

At what holding time does the gate freeze? 1.2 sec

XVII. Effects of Mold Temperature on Part Properties and Gate Freeze Time

A. Observe the effect of mold temperature on part dimensions and weight.

1. Set the Screw Rotation to 25 rpm. [Cycle]
2. Set Mold Temperature for both mold halves to 160°F. [Cycle]
3. Set the Pack/Hold Time to 1.5 seconds. [Cycle}
4. Set Cooling Time to 35 seconds. [Cycle}

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	25
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	160
Mold Stationary Temp	F	160
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	13
Fill Rate 2	in/s	13
Fill Rate 3	in/s	13
Fill Rate 4	in/s	13
Fill Rate 5	in/s	4
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	5500
Pack/Hold Time	s	1.5
Cooling Time	s	35
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	399.9
Fill Time	s	0.21
Cycle Time	s	37.71
Mold Full at VPT	%	95.24
Cushion Size	in	0.231
Part Length	in	6.508
Part Weight	oz	3.141
Screw Run Time	s	11.54

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	
Max Pressure	
No Cushion	
Low Melt	
High Melt	

Cycle Graphs

Cycle: History Edit Setup Change Units User Sessions Page

What is the cycle time? 37.71 sec

What is the part weight? 3.141 oz.

What is the part length? 6.508 in

Determine the gate freeze time at 160° F.

1. Set the Pack/Hold Time to 0.2 second. [Cycle]
2. Continue to increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change.
 - Once the part weight and part length do not change that means the gate has frozen.
 - At this mold temperature (160°F) the part will have warp or “distortion” Disregard this part problem for this exercise.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results																		
Name	Units	Value	Name	Units	Value																
Barrel Temperatures			Fill Rates																		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13																
Middle Zone Temp	F	385	Fill Rate 2	in/s	13																
Front Zone Temp	F	400	Fill Rate 3	in/s	13																
Nozzle Temp	F	400	Fill Rate 4	in/s	13																
Injection Unit			Fill Rate 5	in/s	4																
Screw Rotation	rpm	25	Pressures/Time																		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000																
Screw Back Distance	in	2.48	Ramp Time	s	0																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500																
Mold and Clamp			Pack/Hold Time	s	2																
Mold Moveable Temp	F	160	Cooling Time	s	35																
Mold Stationary Temp	F	160	Mold Open Time	s	1																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																		
<div style="display: flex; justify-content: space-between; margin-top: 10px;"> Cycle History Edit Setup Change Units User Sessions Page </div>			<table border="1"> <tr> <td>Flash</td> <td></td> </tr> <tr> <td>Burn Mark</td> <td></td> </tr> <tr> <td>Size (+/- 0.01 in)</td> <td></td> </tr> <tr> <td>Weld Lines</td> <td></td> </tr> <tr> <td>Short Shot</td> <td></td> </tr> <tr> <td>Warp</td> <td>██████████</td> </tr> <tr> <td>Sink Marks</td> <td>██</td> </tr> <tr> <td>Voids</td> <td></td> </tr> </table>			Flash		Burn Mark		Size (+/- 0.01 in)		Weld Lines		Short Shot		Warp	██████████	Sink Marks	██	Voids	
Flash																					
Burn Mark																					
Size (+/- 0.01 in)																					
Weld Lines																					
Short Shot																					
Warp	██████████																				
Sink Marks	██																				
Voids																					
Cycle Graphs			Machine Alarms																		
			<table border="1"> <tr> <td>Screw Recovery</td> <td>●</td> </tr> <tr> <td>Max Pressure</td> <td>●</td> </tr> <tr> <td>No Cushion</td> <td>●</td> </tr> <tr> <td>Low Melt</td> <td>●</td> </tr> <tr> <td>High Melt</td> <td>●</td> </tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●						
Screw Recovery	●																				
Max Pressure	●																				
No Cushion	●																				
Low Melt	●																				
High Melt	●																				

What is the cycle time? 38.21 sec

What is the part weight? 3.149 oz.

What is the part length? 6.510 in

What is the gate freeze time? 2.0 sec.

Determine the gate freeze time at 60° F.

1. Set the Mold Temperature for both mold halves to 60°F. [Cycle]
2. Set the Pack/Hold Time to 0.2 seconds. [Cycle]
3. Increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.20

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	25	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	1.2
Mold Moveable Temp	F	60	Cooling Time	s	35
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	399.8
Fill Time	s	0.21
Cycle Time	s	37.41
Mold Full at VPT	%	95.20
Cushion Size	in	0.230
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	11.53

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	██████████
Sink Marks	██████████
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

What is the cycle time? 37.41sec

What is the part weight? 3.148 oz.

What is the part length? 6.510 in

What is the gate seal time? 1.2 sec

You have now completed one evaluation of the effects of molding conditions on melt temperature, part weight, part dimensions, machine alarms, and you have observed several molded part defects for this plastic and part.

You can now try to improve your production efficiency for this part. Change the machine controls to reduce the cycle time. You should be able to mold to 100% efficiency or better.

When you begin new mold set-ups, you will solve problems and reduce cycle times using the knowledge you have gained in this lesson. To increase your knowledge of the molding process, you can do a similar evaluation using other plastics.



SimTech™

Student Tutorial Workbook

Getting Started

I. Introduction

This workbook is designed to be used with the Paulson fill rate controlled SimTech™ injection molding simulator. The Student Workbook Tutorial should be taken by all users who are not familiar with how SimTech™ works. If you are already familiar with SimTech™ and how it operates, you can move directly to the SimTech™ lab lessons located at the end of this manual.

The Student Workbook Tutorial is designed to show you how to navigate through the SimTech™ control panel and the effects of each molding machine control on the plastic behavior and on the molded part properties. You will be directed to make specific control changes and then asked to record and explain the results. Provided in the Student section of this manual, is a Student Answer Sheet which you can make copies of for students to write their answers in.

By the end of this tutorial, you should be familiar with how to:

- Make machine control changes
- Cycle the machine
- Read the cycle results
- Identify part problem
- Identify machine alarms
- Will have observed the effects of each control and each alarm

The Student Tutorial Lesson is taken through FreeMold which allows you to pick your machine size, plastic and part. This tutorial lesson uses a 300 ton machine, molding the “cover” using Polystyrene. After completing this tutorial, you can change the type of machine, plastic, or part using the **New Session** button and do a similar evaluation for this new setup.

Note: All pressures shown on the SimTech™ control panel are plastic pressures, not hydraulic oil pressures.

Intentionally left blank

II. Starting Instructions

1. To access SimTech “FreeMold” go to www.paulsonskillbuilder.com
2. Login with your email and password.

3. This will take you to your Skillbuilder Home page.
 - On this page, you will see all the Skillbuilder and SimTech Lab lessons assigned to you. In addition, you will see FreeMold. (You may have to go to page 2 or 3 in the bottom right-hand corner to see FreeMold)

Skillbuilder Home

[My Student Report](#)
[Change My Password](#)

43 records found

Lesson	Assigned	Finished	% Done		
Simtech Lab 12 (Level 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over
Simtech Lab 13 (Level 3)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over
FreeMold	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0%	Continue	Start Over

1 2 3

4. Find FreeMold in your list and click on either Continue or Start Over.
 - For FreeMold, clicking on Continue or Start Over are exactly the same.

FreeMold	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over
----------	-------------------------------------	--------------------------	----	--------------------------	----------------------------

5. You will now be on your User Sessions page.

- Any sessions you created will be listed here
- You can run or edit an existing session, or create a new session

User Sessions

Back New Session

Search Clear 3 records found

Session Name	Updated On	Units	Tolerance	Machine	Part	Plastic					
Test Lesson	2019-10-16 20:22:07	english	precision	300tn	bracket	ABS	Edit Setup	Run	Copy	View History	Delete
Flash lesson	2019-10-15 20:21:40	english	standard	100tn	cover	ABS	Edit Setup	Run	Copy	View History	Delete
Warp & Short Shots Lesson	2019-10-15 20:21:29	english	precision	150tn	bracket	Polypropylene	Edit Setup	Run	Copy	View History	Delete

6. To create a new session, click on New Session.

User Sessions

Back **New Session**

Search Clear 3 records found

Session Name	Updated On	Units	Tolerance	Machine	Part	Plastic					
Test Lesson	2019-10-16 20:22:07	english	precision	300tn	bracket	ABS	Edit Setup	Run	Copy	View History	Delete
Flash lesson	2019-10-15 20:21:40	english	standard	100tn	cover	ABS	Edit Setup	Run	Copy	View History	Delete
Warp & Short Shots Lesson	2019-10-15 20:21:29	english	precision	150tn	bracket	Polypropylene	Edit Setup	Run	Copy	View History	Delete

7. Type in a “Session Name” (we’re using SimTech User Manual) and click “Save And Exit”.

New Session

Exit Without Saving

Session Name:

Setup: NOTE: Machine, Part, and Plastic will be selected on next screen.

Save And Exit



- You will now be on the Setup page. Configure your setup page to match the setup below. When you have finished, click Save and Exit.

Setup

Name

SimTech User M

Enter a name for this session

Standard Cycle Time

30.00

Standard Cycle Time used for Score


Tolerance

loose

loose	in	+/- 0.01
-------	----	----------

Part

cover



Part Length	in	6.500
Part Width	in	6.500
Part Thickness	in	0.080
Part Volume	in^3	5.330
Number of Cavities		2


Units

english

Choose the units to work in

Machine

300tn



Max Injection Press	psi	25000
Max Clamp Force	tons	300
Max Shot Size	in^3	39.300
Max Flow Rate	in^3	25.000

Plastic

Polystyrene



Plastic Type		PS
Low Melt Temp	F	379
High Melt Temp	F	471

- Now Click the Run button and you will see the machine controls page.

User Sessions

Back New Session

Search Clear 5 records found

Session Name	Updated On	Units	Tolerance	Machine	Part	Plastic					
SimTech User Manual	2019-10-23 21:00:34	english	loose	300tn	cover	Polystyrene	Edit Setup	Run	Copy	View History	Delete

10. Enter the process data just as you see below.

- You can type in number values or use the up and down arrows to change the values.

Machine Control Settings

Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	450	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	500	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	30
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

11. Click on the **Cycle** button. Wait for the molding cycle to end.

- You are molding a part with no defects.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	450
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	500
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	445.7
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.90
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.36

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

Navigation buttons: **Cycle** (highlighted), History, Edit Setup, Change Units, User Sessions Page

Intentionally Left Blank



SimTech™

Student Tutorial Workbook

A complete step-by-step tutorial that teaches all about successfully operating **SimTech™** - the injection molding machine simulator.

Intentionally left blank

SimTech™ Tutorial – Student Workbook

I. Effects of Barrel Temperature on Melt Temperature

A. You will now determine the effect on the melt temperature of each of the barrel zone temperatures.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	450
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	500
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	445.7
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.90
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.36

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

What is the melt temperature? _____ °F

II. Determine the Effect of Each Barrel Zone Temperatures on the Melt Temperature

A. You will raise each barrel zone by 20°F to determine which zone has the greatest effect.

1. Raise rear zone barrel temperature to 470°F. [Cycle the machine]

What is the melt temperature? _____ °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	470	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	500	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70		s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	447.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.90
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.37

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

- Raise the middle zone temperature to 470°F and set the rear zone temperature back to 450°F. [Cycle the machine]

What is the melt temperature? _____ °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	450	Fill Rate 1	in/s	2
Middle Zone Temp	F	470	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	35	Pressures/Time		
Screw Back Pressure	psi	500	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

- Flash
- Burn Mark
- Size (+/- 0.01 in)
- Weld Lines
- Short Shot
- Warp
- Sink Marks
- Voids

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Pressure (psi)

Screw Travel (in)

Injection Pressure

3. Raise the front zone barrel temperature and nozzle temperature to 470°F and set the middle zone back to 450°F. [Cycle the machine]

What is the melt temperature? _____ °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	450	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	470	Fill Rate 3	in/s	2
Nozzle Temp	F	470	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	500	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70		s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	458.5
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.87
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.47

Part Problems (most recent cycle to the left)

- Flash
- Burn Mark
- Size (+/- 0.01 in)
- Weld Lines
- Short Shot
- Warp
- Sink Marks
- Voids

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Buttons: Cycle, History, Edit Setup, Change Units, User Sessions Page

Cycle Graphs

Which zone affected the melt temperature the most? _____

Why? _____

4. Typical barrel zone settings for this plastic are: 450°F nozzle, 450°F front, 450°F middle, 400°F rear. Set the zones to these settings. [Cycle the machine]

What is the melt temperature? _____ °F

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	500	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	30
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Cycle Results		
Name	Units	Value
Melt Temp	F	441.7
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.91
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	8.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

III. Determine the Effect of the Back Pressure on the Melt Temperature

A. Increased back pressure causes more heating of the plastic in the barrel.

1. Raise the back pressure and repeat the cycle until melt temperature is the same as the front zone temperature. (i.e. 450°F)

What is the back pressure when the melt temperature is 450°F? _____ psi

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5		
Screw Rotation	rpm	35	Fill Rate 5	in/s	2
Screw Back Pressure	psi	1955	Pressures/Time		
Screw Back Distance	in	2.48	Max Injection Pressure	psi	25000
VPT Setpoint	in	0.35	Ramp Time	s	0
Mold and Clamp			Pack/Hold Pressure	psi	3500
Mold Moveable Temp	F	70	Pack/Hold Time	s	5
Mold Stationary Temp	F	70	Cooling Time	s	30
Clamp Force	tons	300	Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	12.97

Part Problems (most recent cycle to the left)

- Flash
- Burn Mark
- Size (+/- 0.01 in)
- Weld Lines
- Short Shot
- Warp
- Sink Marks
- Voids

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Explain why the melt temperature increased when the back pressure was increased.

Why is it best to have the front zone temperature and the melt temperature the same?

IV. Effects of Screw Back Setting

A. The screw back setting determines how far back the screw returns when it rotates. Screw back setting also controls the cushion size.

1. Set the screw back distance to 3.5” and the VPT setpoint to 1.35”. [Cycle]

What is the present cushion size? _____ in

Is the cushion size all Right? _____

Explain: _____

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	35
Screw Back Pressure	psi	1955
Screw Back Distance	in	3.5
VPT Setpoint	in	1.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	450.2
Fill Time	s	1.09
Cycle Time	s	37.09
Mold Full at VPT	%	95.77
Cushion Size	in	1.251
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	13.04

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

Cycle History: [Cycle] [History] [Edit Setup] [Change Units] [User Sessions Page]

2. Reduce the screw back setting to 2.0” and the VPT setpoint to 0.4”. [Cycle]

What happened? _____

Why? _____

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	35	Max Injection Pressure	psi	25000
Screw Back Pressure	psi	1955	Ramp Time	s	0
Screw Back Distance	in	2	Pack/Hold Pressure	psi	3500
VPT Setpoint	in	0.4	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.8
Fill Time	s	0.83
Cycle Time	s	36.83
Mold Full at VPT	%	71.61
Cushion Size	in	0.000
Part Length	in	6.269
Part Weight	oz	3.128
Screw Run Time	s	11.48

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	■
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

3. Set the screw back position so that the cushion size is between 0.125” and 0.250” [Cycle].

Note: In the ProMolder Series we consider an optimized cushion to be in a range of 5-10% of the total shot size.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results																		
Name	Units	Value	Name	Units	Value																
Barrel Temperatures			Fill Rates																		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2																
Middle Zone Temp	F	450	Fill Rate 2	in/s	2																
Front Zone Temp	F	450	Fill Rate 3	in/s	2																
Nozzle Temp	F	450	Fill Rate 4	in/s	2																
Injection Unit			Fill Rate 5	in/s	2																
Screw Rotation	rpm	35	Pressures/Time																		
Screw Back Pressure	psi	1955	Max Injection Pressure	psi	25000																
Screw Back Distance	in	2.48	Ramp Time	s	0																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500																
Mold and Clamp			Pack/Hold Time	s	5																
Mold Moveable Temp	F	70	Cooling Time	s	30																
Mold Stationary Temp	F	70	Mold Open Time	s	1																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																		
<div style="display: flex; justify-content: space-between;"> Cycle History Edit Setup Change Units User Sessions Page </div>			<table border="1"> <tr><td>Flash</td><td></td></tr> <tr><td>Burn Mark</td><td></td></tr> <tr><td>Size (+/- 0.01 in)</td><td>■</td></tr> <tr><td>Weld Lines</td><td></td></tr> <tr><td>Short Shot</td><td>■</td></tr> <tr><td>Warp</td><td></td></tr> <tr><td>Sink Marks</td><td></td></tr> <tr><td>Voids</td><td></td></tr> </table>			Flash		Burn Mark		Size (+/- 0.01 in)	■	Weld Lines		Short Shot	■	Warp		Sink Marks		Voids	
Flash																					
Burn Mark																					
Size (+/- 0.01 in)	■																				
Weld Lines																					
Short Shot	■																				
Warp																					
Sink Marks																					
Voids																					
Cycle Graphs			Machine Alarms																		
			<table border="1"> <tr><td>Screw Recovery</td><td>●</td></tr> <tr><td>Max Pressure</td><td>●</td></tr> <tr><td>No Cushion</td><td>●</td></tr> <tr><td>Low Melt</td><td>●</td></tr> <tr><td>High Melt</td><td>●</td></tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●						
Screw Recovery	●																				
Max Pressure	●																				
No Cushion	●																				
Low Melt	●																				
High Melt	●																				

What is the screw back position you have set? _____

What is the VPT setpoint you have set? _____

What is the melt temperature? _____ °F

Note: Do not re-adjust back pressure yet.

V. Determine the Effect of Screw RPM on the Melt Temperature

A. Screw rpm can also affect the plastic temperature, but the magnitude of the affect depends on the screw design and the amount of non-Newtonian viscosity change that occurs.

1. Increase screw rpm to 150. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	150
Screw Back Pressure	psi	1955
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	5
Cooling Time	s	30
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	453.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.88
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	2.42

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What is the melt temperature? _____ °F

Why did the melt temperature increase? _____

2. Adjust the back pressure so that the melt temperature is 450°F. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.91

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	3500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.08
Cycle Time	s	37.08
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.510
Part Weight	oz	3.149
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	■
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History Edit Setup Change Units User Sessions Page

Cycle Graphs

What is the back pressure to achieve 450°F melt temperature? _____ psi

VI. Maximum Injection Pressure Alarm

A. The Maximum Injection Pressure Alarm will activate if the machine has tried to exceed its maximum injection pressure.

1. Reduce max injection pressure to 1,100 psi. and reduce the Pack/Hold pressure to 1,000 psi [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	1100
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1000
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	0.00
Cycle Time	s	36.00
Mold Full at VPT	%	94.75
Cushion Size	in	0.330
Part Length	in	6.419
Part Weight	oz	3.170
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash		
Burn Mark		
Size (+/- 0.01 in)	■	■
Weld Lines		
Short Shot	■	■
Warp		
Sink Marks		
Voids		

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Pressure (psi)

Screw Travel (in)

Injection Pressure

Why did the Low Max Injection Pressure alarm occur? _____

2. Raise the max injection pressure to 10,000 psi and the Pack/Hold pressure to 1,700 psi. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.66

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	30
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

Problem	Severity
Flash	None
Burn Mark	None
Size (+/- 0.01 in)	High
Weld Lines	None
Short Shot	High
Warp	None
Sink Marks	None
Voids	None

Machine Alarms

- Screw Recovery:
- Max Pressure:
- No Cushion:
- Low Melt:
- High Melt:

Cycle Graphs

VII. The Screw RPM Alarm

A. The Screw Recovery Alarm will activate if the screw does not rotate fast enough thus, enabling the screw to return to the Screw Back Distance setting before the next shot.

1. Lower the screw speed to 13 rpm. **[Cycle]**

What alarm occurred? _____

Why? _____

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results																																		
Name	Units	Value	Name	Units	Value																																
Barrel Temperatures			Fill Rates																																		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2																																
Middle Zone Temp	F	450	Fill Rate 2	in/s	2																																
Front Zone Temp	F	450	Fill Rate 3	in/s	2																																
Nozzle Temp	F	450	Fill Rate 4	in/s	2																																
Injection Unit			Fill Rate 5	in/s	2																																
Screw Rotation	rpm	13	Pressures/Time																																		
Screw Back Pressure	psi	1335	Max Injection Pressure	psi	10000																																
Screw Back Distance	in	2.48	Ramp Time	s	0																																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700																																
Mold and Clamp			Pack/Hold Time	s	5																																
Mold Moveable Temp	F	70	Cooling Time	s	30																																
Mold Stationary Temp	F	70	Mold Open Time	s	1																																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																																		
<div style="display: flex; justify-content: space-between; width: 100%;"> Cycle History Edit Setup Change Units User Sessions Page </div>			<table border="1"> <tr> <td>Flash</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Burn Mark</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Size (+/- 0.01 in)</td> <td>■</td> <td>■</td> <td>■</td> </tr> <tr> <td>Weld Lines</td> <td>■</td> <td></td> <td>■</td> </tr> <tr> <td>Short Shot</td> <td>■</td> <td>■</td> <td>■</td> </tr> <tr> <td>Warp</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Sink Marks</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Voids</td> <td></td> <td></td> <td></td> </tr> </table>			Flash				Burn Mark				Size (+/- 0.01 in)	■	■	■	Weld Lines	■		■	Short Shot	■	■	■	Warp				Sink Marks				Voids			
Flash																																					
Burn Mark																																					
Size (+/- 0.01 in)	■	■	■																																		
Weld Lines	■		■																																		
Short Shot	■	■	■																																		
Warp																																					
Sink Marks																																					
Voids																																					
Cycle Graphs			Machine Alarms																																		
			<table border="1"> <tr> <td>Screw Recovery</td> <td>●</td> </tr> <tr> <td>Max Pressure</td> <td>●</td> </tr> <tr> <td>No Cushion</td> <td>●</td> </tr> <tr> <td>Low Melt</td> <td>●</td> </tr> <tr> <td>High Melt</td> <td>●</td> </tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●																						
Screw Recovery	●																																				
Max Pressure	●																																				
No Cushion	●																																				
Low Melt	●																																				
High Melt	●																																				

2. Raise rpm to 150. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 80.66

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	1335	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	30
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	450.0
Fill Time	s	1.19
Cycle Time	s	37.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.132
Screw Run Time	s	2.14

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■ ■ ■
Weld Lines	■ ■ ■
Short Shot	■ ■ ■
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

Cycle Graphs

What is the melt temperature? _____ °F

VIII. Determine the Effect of the Mold Closed Time on the Melt Temperature

A. You will explore how the mold closed timer can affect the melt temperature.

1. Reduce mold closed time to 15 seconds. [Cycle]

(the cooling time is the same thing as the mold closed time)

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	1335	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time		
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	442.9
Fill Time	s	1.22
Cycle Time	s	22.22
Mold Full at VPT	%	94.91
Cushion Size	in	0.231
Part Length	in	6.507
Part Weight	oz	3.134
Screw Run Time	s	2.11

Part Problems (most recent cycle to the left)

Flash				
Burn Mark				
Size (+/- 0.01 in)	■	■	■	■
Weld Lines	■	■	■	■
Short Shot	■	■	■	■
Warp				
Sink Marks				
Voids				

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is melt temperature? _____ °F

Why did the melt temperature decrease? _____

2. Use the back pressure to raise the melt temperature to 450°F ±2°. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings			Cycle Results																																																		
Name	Units	Value	Name	Units	Value																																																
Barrel Temperatures			Fill Rates																																																		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2																																																
Middle Zone Temp	F	450	Fill Rate 2	in/s	2																																																
Front Zone Temp	F	450	Fill Rate 3	in/s	2																																																
Nozzle Temp	F	450	Fill Rate 4	in/s	2																																																
Injection Unit			Fill Rate 5	in/s	2																																																
Screw Rotation	rpm	150	Pressures/Time																																																		
Screw Back Pressure	psi	2325	Max Injection Pressure	psi	10000																																																
Screw Back Distance	in	2.48	Ramp Time	s	0																																																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700																																																
Mold and Clamp			Pack/Hold Time	s	5																																																
Mold Moveable Temp	F	70	Cooling Time	s	15																																																
Mold Stationary Temp	F	70	Mold Open Time	s	1																																																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																																																		
<p>Cycle History Edit Setup Change Units User Sessions Page</p>			<table border="1"> <tr><td>Flash</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Burn Mark</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Size (+/- 0.01 in)</td><td>■</td><td>■</td><td>■</td><td>■</td><td>■</td></tr> <tr><td>Weld Lines</td><td>■</td><td>■</td><td>■</td><td>■</td><td>■</td></tr> <tr><td>Short Shot</td><td>■</td><td>■</td><td>■</td><td>■</td><td>■</td></tr> <tr><td>Warp</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Sink Marks</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Voids</td><td></td><td></td><td></td><td></td><td></td></tr> </table>			Flash						Burn Mark						Size (+/- 0.01 in)	■	■	■	■	■	Weld Lines	■	■	■	■	■	Short Shot	■	■	■	■	■	Warp						Sink Marks						Voids					
Flash																																																					
Burn Mark																																																					
Size (+/- 0.01 in)	■	■	■	■	■																																																
Weld Lines	■	■	■	■	■																																																
Short Shot	■	■	■	■	■																																																
Warp																																																					
Sink Marks																																																					
Voids																																																					
Cycle Graphs			Machine Alarms																																																		
			<table border="1"> <tr><td>Screw Recovery</td><td>●</td></tr> <tr><td>Max Pressure</td><td>●</td></tr> <tr><td>No Cushion</td><td>●</td></tr> <tr><td>Low Melt</td><td>●</td></tr> <tr><td>High Melt</td><td>●</td></tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●																																						
Screw Recovery	●																																																				
Max Pressure	●																																																				
No Cushion	●																																																				
Low Melt	●																																																				
High Melt	●																																																				

What is the new back pressure setting? _____ psi

IX. The Back Pressure and No Cushion Alarms

A. Why the back pressure and no cushion alarms come on

1. Raise back pressure to 6000 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	6000	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	473.3
Fill Time	s	0.25
Cycle Time	s	21.25
Mold Full at VPT	%	7.76
Cushion Size	in	0.000
Part Length	in	2.915
Part Weight	oz	3.090
Screw Run Time	s	2.39

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■ ■ ■
Weld Lines	■ ■ ■
Short Shot	■ ■ ■
Warp	
Sink Marks	
Voids	■ ■ ■

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What alarms occurred? _____

Why? _____

2. Reset the back pressure to 2,325 psi. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	2325	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Cooling Time	s	15
Mold Moveable Temp	F	70	Mold Open Time	s	1
Mold Stationary Temp	F	70			
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.19
Cycle Time	s	22.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.57

Part Problems (most recent cycle to the left)

Flash									
Burn Mark									
Size (+/- 0.01 in)									
Weld Lines									
Short Shot									
Warp									
Sink Marks									
Voids									

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History: [Cycle] [History] [Edit Setup] [Change Units] [User Sessions Page]

Cycle Graphs

X. Determine the Effect of Mold Open Time on the Melt Temperature

A. You will explore how the mold open timer can affect the melt temperature.

1. Increase the mold open time to 5 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Fill Rate 5	in/s	2
Screw Rotation	rpm	150	Pressures/Time		
Screw Back Pressure	psi	2325	Max Injection Pressure	psi	10000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	70	Cooling Time	s	15
Mold Stationary Temp	F	70	Mold Open Time	s	5
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	452.0
Fill Time	s	1.19
Cycle Time	s	26.19
Mold Full at VPT	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.59

Part Problems (most recent cycle to the left)

Problem	1	2	3	4	5	6	7	8	9	10
Flash										
Burn Mark										
Size (+/- 0.01 in)										
Weld Lines										
Short Shot										
Warp										
Sink Marks										
Voids										

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

What is the melt temperature? _____ °F

Why did the temperature increase? _____

2. Set the mold open time to 1 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 135.17

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	400
Middle Zone Temp	F	450
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	150
Screw Back Pressure	psi	2325
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.19
Cycle Time	s	22.19
Mold Full at VPT %	%	94.89
Cushion Size	in	0.231
Part Length	in	6.506
Part Weight	oz	3.133
Screw Run Time	s	2.57

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	2
Fill Rate 2	in/s	2
Fill Rate 3	in/s	2
Fill Rate 4	in/s	2
Fill Rate 5	in/s	2
Pressures/Time		
Max Injection Pressure	psi	10000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	
Sink Marks	
Voids	■

Cycle | **History** | **Edit Setup** | **Change Units** | **User Sessions Page**

Cycle Graphs

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

XI. Determine the Effect of the Mold Temperature on the Melt Temperature

A. You will explore how the mold temperature can affect the melt temperature.

1. Set mold temperature to 110°F (both halves). [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	400	Fill Rate 1	in/s	2
Middle Zone Temp	F	450	Fill Rate 2	in/s	2
Front Zone Temp	F	450	Fill Rate 3	in/s	2
Nozzle Temp	F	450	Fill Rate 4	in/s	2
Injection Unit			Pressures/Time		
Screw Rotation	rpm	150	Max Injection Pressure	psi	10000
Screw Back Pressure	psi	2325	Ramp Time	s	0
Screw Back Distance	in	2.48	Pack/Hold Pressure	psi	1700
VPT Setpoint	in	0.35	Pack/Hold Time	s	5
Mold and Clamp			Pressures/Time		
Mold Moveable Temp	F	110	Cooling Time	s	15
Mold Stationary Temp	F	110	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	449.6
Fill Time	s	1.15
Cycle Time	s	22.15
Mold Full at VPT	%	94.86
Cushion Size	in	0.231
Part Length	in	6.505
Part Weight	oz	3.127
Screw Run Time	s	2.57

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	■
Sink Marks	
Voids	■

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

Cycle Graphs

What is the melt temperature? _____ °F

Does the mold temperature affect the melt temperature in the barrel? _____

XII. Determine the Effects of Fill Rates on the Molded Parts

A. You will explore how fill rates can affect the molded parts.

1. Set barrel rear zone to 380°F, middle zone to 385°F, front and nozzle to 400°F [Cycle]
2. Set screw rotation to 65 rpm and screw back pressure to 600 psi. [Cycle]
3. Set mold temperature to 60°F (both halves). [Cycle]
4. Set all fill rates 4.0 in/sec. [Cycle]
5. Set the max injection pressure to 25,000 psi. [Cycle]

Note: This molding machine has a maximum fill rate of 25 inches per second.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 138.79

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	4
Fill Rate 2	in/s	4
Fill Rate 3	in/s	4
Fill Rate 4	in/s	4
Fill Rate 5	in/s	4
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	█
Weld Lines	█
Short Shot	█
Warp	█
Sink Marks	
Voids	█

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

6. Set Fill Rates 1, 2, 3, and 4 to 10.0 in/sec.
7. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 140.75

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	10
Fill Rate 2	in/s	10
Fill Rate 3	in/s	10
Fill Rate 4	in/s	10
Fill Rate 5	in/s	4
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Cycle Graphs

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	■
Short Shot	■
Warp	■
Sink Marks	
Voids	■

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What changes occurred to the molded parts? _____

8. Set Fill Rates 1, 2, 3, and 4 to 3.0 in/sec.
9. Set Fill Rate 5 to 6.0 in/sec. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	3
Middle Zone Temp	F	385	Fill Rate 2	in/s	3
Front Zone Temp	F	400	Fill Rate 3	in/s	3
Nozzle Temp	F	400	Fill Rate 4	in/s	3
Injection Unit			Fill Rate 5	in/s	6
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

Flash				
Burn Mark	■			
Size (+/- 0.01 in)			■	■
Weld Lines			■	■
Short Shot				
Warp		■		
Sink Marks				
Voids				■

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Buttons: Cycle, History, Edit Setup, Change Units, User Sessions Page

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What happened to part weight and dimensions when the final Fill Rate 5 is very fast?

Why? _____

10. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec.

11. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

- You should get a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.24

Machine Control Settings			Cycle Results																																																		
Name	Units	Value	Name	Units	Value																																																
Barrel Temperatures			Fill Rates																																																		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13																																																
Middle Zone Temp	F	385	Fill Rate 2	in/s	13																																																
Front Zone Temp	F	400	Fill Rate 3	in/s	13																																																
Nozzle Temp	F	400	Fill Rate 4	in/s	13																																																
Injection Unit			Fill Rate 5	in/s	4																																																
Screw Rotation	rpm	65	Pressures/Time																																																		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000																																																
Screw Back Distance	in	2.48	Ramp Time	s	0																																																
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700																																																
Mold and Clamp			Pack/Hold Time	s	5																																																
Mold Moveable Temp	F	60	Cooling Time	s	15																																																
Mold Stationary Temp	F	60	Mold Open Time	s	1																																																
Clamp Force	tons	300	Part Problems (most recent cycle to the left)																																																		
<div style="display: flex; justify-content: space-between;"> Cycle History Edit Setup Change Units User Sessions Page </div>			<table border="1"> <tr><td>Flash</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Burn Mark</td><td>■</td><td></td><td></td><td></td><td></td></tr> <tr><td>Size (+/- 0.01 in)</td><td></td><td></td><td></td><td></td><td>■</td></tr> <tr><td>Weld Lines</td><td></td><td></td><td></td><td></td><td>■</td></tr> <tr><td>Short Shot</td><td></td><td></td><td></td><td></td><td>■</td></tr> <tr><td>Warp</td><td></td><td>■</td><td></td><td></td><td></td></tr> <tr><td>Sink Marks</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Voids</td><td></td><td></td><td></td><td></td><td>■</td></tr> </table>			Flash						Burn Mark	■					Size (+/- 0.01 in)					■	Weld Lines					■	Short Shot					■	Warp		■				Sink Marks						Voids					■
Flash																																																					
Burn Mark	■																																																				
Size (+/- 0.01 in)					■																																																
Weld Lines					■																																																
Short Shot					■																																																
Warp		■																																																			
Sink Marks																																																					
Voids					■																																																
Cycle Graphs			Machine Alarms																																																		
			<table border="1"> <tr><td>Screw Recovery</td><td>●</td></tr> <tr><td>Max Pressure</td><td>●</td></tr> <tr><td>No Cushion</td><td>●</td></tr> <tr><td>Low Melt</td><td>●</td></tr> <tr><td>High Melt</td><td>●</td></tr> </table>			Screw Recovery	●	Max Pressure	●	No Cushion	●	Low Melt	●	High Melt	●																																						
Screw Recovery	●																																																				
Max Pressure	●																																																				
No Cushion	●																																																				
Low Melt	●																																																				
High Melt	●																																																				

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What happened to part weight and dimensions when final Fill Rate 5 is reduced? _____

Why? _____

Fill Rates Conclusions:

- Very high fill rates require high injection pressures.
- Of all the fill rates, the final Fill Rate 5 has the greatest effect on part dimensions and weight.

2. Reduce clamp force to 65 tons. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	65
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	60
Mold Stationary Temp	F	60
Clamp Force	tons	65

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	4
Fill Rate 2	in/s	4
Fill Rate 3	in/s	4
Fill Rate 4	in/s	4
Fill Rate 5	in/s	8
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	1700
Pack/Hold Time	s	5
Cooling Time	s	15
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	<input checked="" type="checkbox"/>
Burn Mark	<input checked="" type="checkbox"/>
Size (+/- 0.01 in)	<input checked="" type="checkbox"/>
Weld Lines	<input type="checkbox"/>
Short Shot	<input type="checkbox"/>
Warp	<input checked="" type="checkbox"/>
Sink Marks	<input type="checkbox"/>
Voids	<input type="checkbox"/>

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Cycle | History | Edit Setup | Change Units | User Sessions Page

What change occurred in the defects present? _____

Why? _____

3. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec. Set Fill Rate 5 to 4.0 in/sec. [Cycle]

4. Set the Clamp Force to 75 tons. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.24

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	1700
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	75	Part Problems (most recent cycle to the left)		

Flash: [Bar chart showing 4 red bars]

Burn Mark: [Bar chart showing 3 red bars]

Size (+/- 0.01 in): [Bar chart showing 1 red bar]

Weld Lines: [Bar chart showing 0 red bars]

Short Shot: [Bar chart showing 0 red bars]

Warp: [Bar chart showing 1 red bar]

Sink Marks: [Bar chart showing 0 red bars]

Voids: [Bar chart showing 0 red bars]

Machine Alarms

- Screw Recovery: [Green dot]
- Max Pressure: [Green dot]
- No Cushion: [Green dot]
- Low Melt: [Green dot]
- High Melt: [Green dot]

Cycle: History Edit Setup Change Units User Sessions Page

Cycle Graphs

What happened to the flash? _____

Why? _____

What conclusions would you make concerning the effects of clamp force and fill rate on burn marks and flash? _____

XIV. Determine the Effects of Pack/Hold pressure on the Molded Part Properties

A. Now we'll examine the effect of pack/hold pressure on part weight and dimensions.

1. Increase the clamp force to 300 tons. (This will avoid flash when we increase the pack/hold pressure.) [Cycle]
2. Increase the pack/hold pressure to 5,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.46

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle History: Cycle | History | Edit Setup | Change Units | User Sessions Page

Cycle Graphs

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Why did the part size increase? _____

3. Reduce the pack/hold pressure to 4,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.45

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	4500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	■
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Why did the part dimensions and weight decrease when the pack/hold pressure was reduced?

4. Reduce the pack/hold pressure to 6,000 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	6000
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

- Flash:
- Burn Mark:
- Size (+/- 0.01 in):
- Weld Lines:
- Short Shot:
- Warp:
- Sink Marks:
- Voids:

Machine Alarms

- Screw Recovery:
- Max Pressure:
- No Cushion:
- Low Melt:
- High Melt:

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Notice the part dimensions are now out of spec. Why did this happen?

5. Increase the pack/hold pressure to 2,500 psi. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.40

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	2500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

Problem	Count
Flash	1
Burn Mark	2
Size (+/- 0.01 in)	2
Weld Lines	0
Short Shot	0
Warp	0
Sink Marks	0
Voids	0

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

XV. Determine the Effects of Pack/Hold Time on the Molded Part Properties

A. Now we'll examine the effect of pack/hold time on part weight and dimensions.

Note: Too short a holding time can cause “discharge”.

1. Set the Pack/Hold Pressure back to 5,500 psi.. [Cycle]

- You should have a good part.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 141.46

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	5
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	400.2
Fill Time	s	0.21
Cycle Time	s	21.21
Mold Full at VPT	%	95.19
Cushion Size	in	0.230
Part Length	in	6.510
Part Weight	oz	3.148
Screw Run Time	s	4.32

Part Problems (most recent cycle to the left)

Flash	<input type="checkbox"/>
Burn Mark	<input type="checkbox"/>
Size (+/- 0.01 in)	<input type="checkbox"/>
Weld Lines	<input type="checkbox"/>
Short Shot	<input type="checkbox"/>
Warp	<input type="checkbox"/>
Sink Marks	<input type="checkbox"/>
Voids	<input type="checkbox"/>

Machine Alarms

Screw Recovery	<input type="checkbox"/>
Max Pressure	<input type="checkbox"/>
No Cushion	<input type="checkbox"/>
Low Melt	<input type="checkbox"/>
High Melt	<input type="checkbox"/>

Cycle Graphs

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

2. Set pack/hold time to 3 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 156.19

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	3
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Cycle Graphs

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	■
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

3. Set holding time to 1 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 174.34

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	1
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Part Problems (most recent cycle to the left)

Name	Units	Value
Melt Temp	F	398.1
Fill Time	s	0.21
Cycle Time	s	17.21
Mold Full at VPT	%	95.21
Cushion Size	in	0.231
Part Length	in	6.509
Part Weight	oz	3.144
Screw Run Time	s	4.32

Machine Alarms

- Screw Recovery
- Max Pressure
- No Cushion
- Low Melt
- High Melt

Cycle Graphs

Buttons: Cycle, History, Edit Setup, Change Units, User Sessions Page

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

XVI. Find the Gate Freeze Time

1. Set the Pack/Hold Time to 0.1 second. **[Cycle]**
2. Continue to increase the Pack/Hold Time by 0.1 seconds until you find that the part weight and length does not change.
 - Once the part weight and part length do not change that means the gate has frozen.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 172.33

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	65	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	1.2
Mold Moveable Temp	F	60	Cooling Time	s	15
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300	Part Problems (most recent cycle to the left)		
<div style="display: flex; justify-content: space-between;"> Cycle History Edit Setup Change Units User Sessions Page </div>			Flash Burn Mark Size (+/- 0.01 in) Weld Lines Short Shot Warp Sink Marks Voids		
Cycle Graphs			Machine Alarms		
			Screw Recovery <input type="checkbox"/> Max Pressure <input type="checkbox"/> No Cushion <input type="checkbox"/> Low Melt <input type="checkbox"/> High Melt <input type="checkbox"/>		

At what holding time does the gate freeze? _____ sec

XVII. Effects of Mold Temperature on Part Properties and Gate Freeze Time

A. Observe the effect of mold temperature on part dimensions and weight.

1. Set the Screw Rotation to 25 rpm. [Cycle]
2. Set Mold Temperature for both mold halves to 160°F. [Cycle]
3. Set the Pack/Hold Time to 1.5 seconds. [Cycle]
4. Set Cooling Time to 35 seconds. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	380
Middle Zone Temp	F	385
Front Zone Temp	F	400
Nozzle Temp	F	400
Injection Unit		
Screw Rotation	rpm	25
Screw Back Pressure	psi	600
Screw Back Distance	in	2.48
VPT Setpoint	in	0.35
Mold and Clamp		
Mold Moveable Temp	F	160
Mold Stationary Temp	F	160
Clamp Force	tons	300

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	13
Fill Rate 2	in/s	13
Fill Rate 3	in/s	13
Fill Rate 4	in/s	13
Fill Rate 5	in/s	4
Pressures/Time		
Max Injection Pressure	psi	25000
Ramp Time	s	0
Pack/Hold Pressure	psi	5500
Pack/Hold Time	s	1.5
Cooling Time	s	35
Mold Open Time	s	1

Name	Units	Value
Melt Temp	F	399.9
Fill Time	s	0.21
Cycle Time	s	37.71
Mold Full at VPT	%	95.24
Cushion Size	in	0.231
Part Length	in	6.508
Part Weight	oz	3.141
Screw Run Time	s	11.54

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

Screw Recovery	
Max Pressure	
No Cushion	
Low Melt	
High Melt	

Cycle Graphs

Cycle History: Cycle History Edit Setup Change Units User Sessions Page

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Determine the gate freeze time at 160° F.

1. Set the Pack/Hold Time to 0.2 second. [Cycle]
2. Continue to increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change.
 - Once the part weight and part length do not change that means the gate has frozen.
 - At this mold temperature (160°F) the part will have warp or “distortion”. Disregard this part problem for this exercise.

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 0.00

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	25	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	0.2
Mold Moveable Temp	F	160	Cooling Time	s	35
Mold Stationary Temp	F	160	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	399.6
Fill Time	s	0.21
Cycle Time	s	36.41
Mold Full at VPT	%	95.24
Cushion Size	in	0.231
Part Length	in	6.497
Part Weight	oz	3.093
Screw Run Time	s	11.53

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	■ ■ ■ ■ ■ ■ ■ ■
Sink Marks	■ ■ ■ ■ ■ ■ ■ ■
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What is the gate freeze time? _____ sec.

Determine the gate freeze time at 60° F.

1. Set the Mold Temperature for both mold halves to 60°F. [Cycle]
2. Set the Pack/Hold Time to 0.2 seconds. [Cycle]
3. Increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change. [Cycle]

Session Name: SimTech User Manual Machine: 300tn Part: cover Plastic: Polystyrene Tolerance: +/- 0.01 in Standard Cycle Time: 30.0 SCORE: 82.40

Machine Control Settings			Cycle Results		
Name	Units	Value	Name	Units	Value
Barrel Temperatures			Fill Rates		
Rear Zone Temp	F	380	Fill Rate 1	in/s	13
Middle Zone Temp	F	385	Fill Rate 2	in/s	13
Front Zone Temp	F	400	Fill Rate 3	in/s	13
Nozzle Temp	F	400	Fill Rate 4	in/s	13
Injection Unit			Fill Rate 5	in/s	4
Screw Rotation	rpm	25	Pressures/Time		
Screw Back Pressure	psi	600	Max Injection Pressure	psi	25000
Screw Back Distance	in	2.48	Ramp Time	s	0
VPT Setpoint	in	0.35	Pack/Hold Pressure	psi	5500
Mold and Clamp			Pack/Hold Time	s	0.2
Mold Moveable Temp	F	60	Cooling Time	s	35
Mold Stationary Temp	F	60	Mold Open Time	s	1
Clamp Force	tons	300			

Name	Units	Value
Melt Temp	F	399.6
Fill Time	s	0.21
Cycle Time	s	36.41
Mold Full at VPT	%	95.21
Cushion Size	in	0.231
Part Length	in	6.500
Part Weight	oz	3.108
Screw Run Time	s	11.53

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.01 in)	
Weld Lines	
Short Shot	
Warp	■ ■ ■
Sink Marks	■
Voids	

Machine Alarms

Screw Recovery	●
Max Pressure	●
No Cushion	●
Low Melt	●
High Melt	●

Cycle Graphs

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What is the gate seal time? _____ sec

You have now completed one evaluation of the effects of molding conditions on melt temperature, part weight, part dimensions, machine alarms, and you have observed several molded part defects for this plastic and part.

You can now try to improve your production efficiency for this part. Change the machine controls to reduce the cycle time. You should be able to mold to 100% efficiency or better.

When you begin new mold set-ups, you will solve problems and reduce cycle times using the knowledge you have gained in this lesson. To increase your knowledge of the molding process, you can do a similar evaluation using other plastics.



SimTech™

Student Answer Sheet

This answer sheet can be used to make copies for each student to write down their answers from the Student Tutorial Workbook.

This answer sheet can also be download from our website at:

www.paulsontraining.com/support-center

Intentionally Left Blank

Name: _____

Student Answer Sheet

I. Effects of Barrel Temperature on Melt Temperature

What is the melt temperature? _____ °F

II. Determine the Effect of Each Barrel Zone Temperatures on the Melt Temperature

A. You will raise each barrel zone by 20°F to determine which zone has the greatest effect.

1. Raise rear zone barrel temperature to 470°F.

What is the melt temperature? _____ °F

2. Raise the middle zone temperature to 470°F and set the rear zone temperature back to 450°F.

What is the melt temperature? _____ °F

3. Raise the front zone barrel temperature and nozzle temperature to 470°F and set the middle zone back to 450°F.

What is the melt temperature? _____ °F

Which zone affected the melt temperature the most? _____

Why? _____

4. Typical barrel zone settings for this plastic are: 450°F nozzle, 450°F front, 450°F middle, 400°F rear. Set the zones to these settings.

What is the melt temperature? _____ °F

III. Determine the Effect of the Back Pressure on the Melt Temperature

A. Increased back pressure causes more heating of the plastic in the barrel.

1. Raise the back pressure and repeat the cycle until melt temperature is the same as the front zone temperature. (i.e. 450°F)

What is the back pressure when the melt temperature is 450°F? _____ psi

Explain why the melt temperature increased when the back pressure was increased.

Why is it best to have the front zone temperature and the melt temperature the same?

IV. Effects of Screw Back Setting

A. The screw back setting determines how far back the screw returns when it rotates. Screw back setting also controls the cushion size.

1. Set the screw back distance to 3.5" and the VPT setpoint to 1.35".

What is the present cushion size? _____ in

Is the cushion size all Right? _____

Explain: _____

2. Reduce the screw back setting to 2.0" and the VPT setpoint to 0.4".

What happened? _____

Why? _____

3. Set the screw back position so that the cushion size is between 0.125" and 0.250".

What is the screw back position you have set? _____

What is the VPT setpoint you have set? _____

What is the melt temperature? _____ °F

V. Determine the Effect of Screw RPM on the Melt Temperature

A. Screw rpm can also affect the plastic temperature, but the magnitude of the affect depends on the screw design and the amount of non-Newtonian viscosity change that occurs.

1. Increase screw rpm to 150.

What is the melt temperature? _____ °F

Why did the melt temperature increase? _____

2. Adjust the back pressure so that the melt temperature is 450°F.

What is the back pressure to achieve 450°F melt temperature? _____ psi

VI. Maximum Injection Pressure Alarm

A. The Maximum Injection Pressure Alarm will activate if the machine has tried to exceed its maximum injection pressure.

1. Reduce max injection pressure to 1,100 psi. and reduce the Pack/Hold pressure to 1,000 psi

Why did the Low Max Injection Pressure alarm occur? _____

VII. The Screw RPM Alarm

A. The Screw Recovery Alarm will activate if the screw does not rotate fast enough thus, enabling the screw to return to the Screw Back Distance setting before the next shot.

1. Lower the screw speed to 13 rpm.

What alarm occurred? _____

Why? _____

2. Raise rpm to 150.

What is the melt temperature? _____ °F

VIII. Determine the Effect of the Mold Closed Time on the Melt Temperature

A. You will explore how the mold closed timer can affect the melt temperature.

1. Reduce mold closed time to 15 seconds.

What is melt temperature? _____ °F

Why did the melt temperature decrease? _____

2. Use the back pressure to raise the melt temperature to 450°F ±2°.

What is the new back pressure setting? _____ psi

IX. The Back Pressure and No Cushion Alarms

A. Why the back pressure and no cushion alarms come on

1. Raise back pressure to 6000 psi.

What alarms occurred? _____

Why? _____

X. Determine the Effect of Mold Open Time on the Melt Temperature

A. You will explore how the mold open timer can affect the melt temperature.

1. Increase the mold open time to 5 seconds.

What is the melt temperature? _____ °F

Why did the temperature increase? _____

XI. Determine the Effect of the Mold Temperature on the Melt Temperature

A. You will explore how the mold temperature can affect the melt temperature.

1. Set mold temperature to 110°F (both halves).

What is the melt temperature? _____ °F

Does the mold temperature affect the melt temperature in the barrel? _____

XII. Determine the Effects of Fill Rates on the Molded Parts

A. You will explore how fill rates can affect the molded parts.

1. Set barrel rear zone to 380°F, middle zone to 385°F, front and nozzle to 400°F
2. Set screw rotation to 65 rpm and screw back pressure to 600 psi.
3. Set mold temperature to 60°F (both halves).
4. Set all fill rates 4.0 in/sec.
5. Set the max injection pressure to 25,000 psi.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

6. Set Fill Rates 1, 2, 3, and 4 to 10.0 in/sec.

7. Set Fill Rate 5 to 4.0 in/sec.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What changes occurred to the molded parts? _____

8. Set Fill Rates 1, 2, 3, and 4 to 3.0 in/sec.

9. Set Fill Rate 5 to 6.0 in/sec.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What happened to part weight and dimensions when the final Fill Rate 5 is very fast?

Why? _____

10. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec.

11. Set Fill Rate 5 to 4.0 in/sec.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What happened to part weight and dimensions when final Fill Rate 5 is reduced?

Why? _____

XIII. Determine the Effects of Clamp Force Setting and Fill Rates on Burn Marks and Flash

A. How does clamp force and the fill rate settings affect burn marks and flash?

1. Set Fill Rates 1, 2, 3, and 4 to 4.0 in/sec. Set Fill Rate 5 to 8.0 in/sec

What molded part defect occurred? _____

Why? _____

2. Reduce clamp force to 65 tons.

What change occurred in the defects present? _____

Why? _____

3. Set Fill Rates 1, 2, 3, and 4 to 13.0 in/sec. Set Fill Rate 5 to 4.0 in/sec.

4. Set the Clamp Force to 75 tons.

What happened to the flash? _____

Why? _____

What conclusions would you make concerning the effects of clamp force and fill rate on burn marks and flash? _____

XIV. Determine the Effects of Pack/Hold pressure on the Molded Part Properties

A. Now we'll examine the effect of pack/hold pressure on part weight and dimensions.

1. Increase the clamp force to 300 tons. (This will avoid flash when we increase the pack/hold pressure.)
2. Increase the pack/hold pressure to 5,500 psi.

What is the fill time? _____sec

What is the cycle time? _____sec

What is the part weight? _____oz.

What is the part length? _____in

Why did the part size increase? _____

3. Reduce the pack/hold pressure to 4,500 psi.

What is the fill time? _____sec

What is the cycle time? _____sec

What is the part weight? _____oz.

What is the part length? _____in

Why did the part dimensions and weight decrease when the pack/hold pressure was reduced?

4. Reduce the pack/hold pressure to 6,000 psi.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Notice the part dimensions are now out of spec. Why did this happen?

5. Increase the pack/hold pressure to 2,500 psi.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

XV. Determine the Effects of Pack/Hold Time on the Molded Part Properties

A. Now we'll examine the effect of pack/hold time on part weight and dimensions.

1. Set the Pack/Hold Pressure back to 5,500 psi..

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

2. Set pack/hold time to 3 seconds.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

3. Set holding time to 1 seconds.

What is the fill time? _____ sec

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Is there any change in the molded parts? _____

XVI. Find the Gate Freeze Time

1. Set the Pack/Hold Time to 0.1 second.
2. Continue to increase the Pack/Hold Time by 0.1 seconds until you find that the part weight and length does not change.

At what holding time does the gate freeze? _____ sec

XVII. Effects of Mold Temperature on Part Properties and Gate Freeze Time

- A. Observe the effect of mold temperature on part dimensions and weight.

1. Set the Screw Rotation to 25 rpm.
2. Set Mold Temperature for both mold halves to 160°F.
3. Set the Pack/Hold Time to 1.5 seconds.
4. Set Cooling Time to 35 seconds.

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

Determine the gate freeze time at 160° F.

1. Set the Pack/Hold Time to 0.2 second.
2. Continue to increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change.

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What is the gate freeze time? _____ sec.

Determine the gate freeze time at 60° F.

1. Set the Mold Temperature for both mold halves to 60°F.
2. Set the Pack/Hold Time to 0.2 seconds.
3. Increase the Pack/Hold Time by 0.2 seconds until you find that the part weight and length does not change.

What is the cycle time? _____ sec

What is the part weight? _____ oz.

What is the part length? _____ in

What is the gate seal time? _____ sec



SimTech™

How to Take the SimTech™ Virtual Lab Lessons

Getting Started

It is now time to apply what you have learned from taking the course lessons. SimTech lab lessons can be taken in any order. We suggest you start with the lessons marked as “Level 1” and work your way up to the “Level 4” labs.

Note: If you are not familiar with how to use SimTech, take the Student Workbook Tutorial first before attempting the Lab Lessons.


Unlike the Skillbuilder lessons you have already taken, the SimTech lab lessons do not have any restrictions on the machine controls. You can change any control you want.

You will benefit the most from these lessons by following the directions carefully. Each lab has a certain set of criteria that needs to be met in order to “complete” a lesson. You will practice machine setup, molded-part problem solving, and cycle time reduction. As you have learned in our training lessons, it is the four basic plastic variables that determine the molded part properties. By understanding how the machine controls affect the four basic plastic variables, you will begin to understand how to fix part problems, and how to set up the most efficient process.


Intentionally Left Blank

As you have learned in the training lessons, you should approach these problems in a scientific and systematic way.

1. Identify the problem(s).
2. Determine which of the four processing variables is causing the problem.
3. Determine which machine controls affect the processing variable(s) in step 2.
4. Make one control change and then Cycle the machine to see the effects of the control change.
5. Continue to make control changes (cycling after each machine control adjustment) until the problem is solved.
6. Then move onto the next problem and follow the same procedure.



1. Login at www.paulsonskillbuilder.com
 - Your administrator will provide you with your password.



The screenshot shows the login interface for Paulson Training Programs, Inc. At the top is the company logo. Below it, the word "Login" is centered. There are two input fields: "E-mail:" and "Password:". Below the password field is a checkbox labeled "Remember me (for 30 days)". At the bottom of the form is a teal button labeled "Login".

2. Scroll down until you see the SimTech Lab Lesson you want to take and click on "Continue" or "Start Over"
 - "Start Over" will reset the machine controls to their starting values
 - "Continue" loads up your last machine control setting for this lesson

Simtech Lab 1 (Level 1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over
Simtech Lab 2 (Level 1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over
Simtech Lab 3 (Level 1)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	0%	Continue	Start Over

3. You will see the control panel and your machine setup. You must click on **“Cycle”** to view the outputs of the current machine control settings.
4. Review the lab lesson from the binder to understand the problems you are trying to solve and the criteria for completing that lesson.

Session Name: simtechlab01 Machine: 300tn Part: cover Plastic: ABS Tolerance: +/- 0.005 in Standard Cycle Time: 20.0 SCORE: 0.00

Machine Control Settings

Name	Units	Value
Barrel Temperatures		
Rear Zone Temp	F	350
Middle Zone Temp	F	400
Front Zone Temp	F	450
Nozzle Temp	F	450
Injection Unit		
Screw Rotation	rpm	60
Screw Back Pressure	psi	300
Screw Back Distance	in	2.35
VPT Setpoint	in	0.21
Mold and Clamp		
Mold Moveable Temp	F	70
Mold Stationary Temp	F	70
Clamp Force	tons	220

Cycle Results

Name	Units	Value
Fill Rates		
Fill Rate 1	in/s	6
Fill Rate 2	in/s	6
Fill Rate 3	in/s	6
Fill Rate 4	in/s	6
Fill Rate 5	in/s	6
Pressures/Time		
Max Injection Pressure	psi	20000
Ramp Time	s	0
Pack/Hold Pressure	psi	3500
Pack/Hold Time	s	3
Cooling Time	s	15
Mold Open Time	s	1

Part Problems (most recent cycle to the left)

Flash	
Burn Mark	
Size (+/- 0.005 in)	
Weld Lines	
Short Shot	
Warp	
Sink Marks	
Voids	

Machine Alarms

- Screw Recovery ●
- Max Pressure ●
- No Cushion ●
- Low Melt ●
- High Melt ●

Cycle Graphs

Navigation: Cycle | History | View Setup | Change Units | Reset Controls | Home Page

Intentionally Left Blank

Lab 1 - Solving Burnmarks (Level 1)

Solving Burnmarks

For this challenge, you are molding a square cover. This customer's dimensional specifications for this rectangular cover part are 6.500" X 6.500" plus or minus 0.005". The plastic you are using is ABS on a 300 ton machine. Your part has a burnmark. The standard (quoted) cycle time for this job is 24 seconds. The part tolerance for this job is $\pm.005$.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 1"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a Burnmark problem.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

Note: If you hover over the red block next to the part problem, you will see a number telling you the severity of your problem.

To complete this lesson:

Solve the burnmark problem two different ways.

1. Solve the burnmark by adjusting the Fill rate controls.
 - a. Once you have solved the burnmark with Fill Rate, click the "Reset Control" button and **Cycle** the machine. This will reset your controls to the original settings and you should see a burnmark again.
2. Solve the burnmark by using the clamp force.

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 2 - Solving Flash - (Level 1)

Solving Flash

For this challenge, you are molding a square cover. This customer's dimensional specifications for this rectangular cover part are 6.500" X 6.500" plus or minus 0.005". The plastic you are using is ABS on a 300 ton machine. Your part has flash. The standard (quoted) cycle time for this job is 24 seconds. The part tolerance for this job is ± 0.005 .

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 2"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a slight Flash problem.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

Note: If you hover over the red block next to the part problem, you will see a number telling you the severity of your problem.

To complete this lesson:

Solve the flash problem two different ways.

1. Solve flash by adjusting one of the Fill rate controls.
 - a. Once you have solved the flash with Fill Rate, click the "Reset Control" button and **Cycle** the machine. This will reset your controls to the original settings and you should see flash again.
2. Solve flash by using the least clamp force possible.

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 3 - Solving Sink Mark and Dimension Problems (Level 1)

Solving Sink Mark and Dimension Problems

For this challenge, you are molding a frame. This customer's dimensional specifications for the part are 12.00" X 4.00" with a tolerance of ± 0.005 ". The plastic you are using is ABS on a 300 ton machine. Your part has sink marks and is below the length specification. The standard (quoted) cycle time for this job is 65 seconds.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 3"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a sink mark problem and your part size is too small.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 65 seconds or less

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 4 - Solve Burnmarks, Dimensional, Sink Mark Problems & Process Optimization (Level 3)

Solve Burnmarks, Dimensional, Sink Mark Problems & Process Optimization

You are molding the part called a bezel out of polystyrene using a 300 ton molding machine.

You will see under the **Cycle Results**, the “Mold Full at VPT” is 90.05%. This VPT setting is not optimized. You’ll have to correct this. The VPT should occur when the mold is between 94% - 96% full. The part has some problems. The part is burning and has a sink mark. The part is also out of specification. Notice for this part, the tolerance is only ± 0.002 ”.

Burning is a critical part problem and must be addressed first in the optimization process. This is because burning creates a high probability of tool damage. Once the burning problem has been corrected, then proceed to the sink mark, optimizing the VPT, cycle time and part dimensions.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson “Lab 4”
3. “Cycle” the machine.
4. Begin changing machine controls one at a time to solve the part problems and get the cycle time to 23 seconds or below.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 23 seconds or less

In addition to solving all part problems and getting your cycle time to 23 seconds or below, you must also meet the below “good molding practices” criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be $\pm 2^{\circ}\text{F}$ of front zone barrel temperature

NOTE: Only make one control change at a time and then click the “Cycle” button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 5 - Solving Flash, Burnmarks, and Dimension Problems (Level 2)

Solving Flash, Burnmarks, and Dimension problems

We are molding a square cover. This customer's dimensional specifications for this rectangular cover part are 6.500" X 6.500". The plastic you are using is Polystyrene on a 300 ton machine. Your part has flash, burnmarks, and is out of dimension, it is too big. The standard (quoted) cycle time for this job is 14 seconds. The part tolerance for this job is 6.500" \pm .005.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 5"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a Flash problem, Burn mark problem, and dimensional problem.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 14 seconds or less

In addition to the above requirements, you must also meet the below "good molding practices" criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be \pm 2°F of front zone barrel temperature

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 6 Solving Voids and Warp (Level 2)

Solving Voids and Warp

We are molding a cover out of ABS plastic on a 300 ton machine. Your part has voids and warp. The standard (quoted) cycle time for this job is 23 seconds. The part tolerance for this job is 6.500" ±.005.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 6"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a warp and voids problem.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems
- Achieve a cycle time of 23 seconds or less

In addition to the above conditions, you must also meet the below "good molding practices" criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be ±2°F of front zone barrel temperature

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 7 - Solving Warp, Sinkmarks, and Dimensional Problems (Level 2)

Solving Warp, Sinkmarks, and Dimensional Problems

We are molding a part called a bezel out of Polystyrene on a 300 ton machine. The customer's specifications for this part are 8.000" x 8.000". The part is too small, it has sink marks and it is warping. The standard (quoted) cycle time for this job is 30 seconds. The part tolerance for this job is $\pm .005$. You must solve the part problems and then optimize the cycle. Of the three 'good molding practices' two of the conditions are already met. The Mold Full at VPT is currently at 94.89% which is within our specification of 94-96%. The cushion size is less than 10% of the screw back distance, again within our 'good molding practices' specifications. However, the melt temperature is 427.7°, not within 2°F of the Front Zone and Nozzle temp. setting. This will need to be fixed.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 7"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have warp, sinkmarks, and dimensions problems.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 27 seconds or less

In addition to solving all part problems and getting your cycle time to 23 seconds or below, you must also meet the below "good molding practices" criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be $\pm 2^\circ\text{F}$ of front zone barrel temperature

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in Simtech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 8 - Solving Sink Marks, Warp and Dimensions Problems (Level 4)

Solving Sink Marks and Dimensions Problems

We are molding a frame. This customer's dimensional specifications for part are 12.00" X 4.00" plus or minus 0.005". The plastic you are using is ABS on a 300 ton machine. Your part has sink marks and a dimensional problem, it is too small. The standard (quoted) cycle time for this job is 65 seconds. The part tolerance for this job is ± 0.005 .

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson "Lab 8"
3. "Cycle" the machine.
4. After you cycle the machine you will see under Part Problems you have a sink mark problem and a size problem.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 65 seconds or less

In addition to solving all part problems and getting your cycle time to 35 seconds or below, you must also meet the below "good molding practices" criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be $\pm 2^{\circ}\text{F}$ of front zone barrel temperature

NOTE: Only make one control change at a time and then click the "Cycle" button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 9 - Optimize the Process and Reduce Cycle Time (Level 3)

Optimize the Process and Reduce Cycle Time

In this set-up, we are already making parts without any defects but the machine settings are not optimized. Your job is to eliminate all part problems, reduce cycle time, and set the controls to “good molding practices” conditions.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson “Lab 9”
3. “Cycle” the machine.
4. You will not see any part problems or machine alarms but your cycle time is too high.
5. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 14 seconds or less

Meet “good molding practices” criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be $\pm 2^{\circ}\text{F}$ of front zone barrel temperature

NOTE: Only make one control change at a time and then click the “Cycle” button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.

Lab 10 - Solving Flash, Dimensional, and Warp problems & VPT (Level 2)

Solving Flash, Dimensional, and Warp problems & VPT

We are molding a cell cover out of ABS plastic on a 150 ton machine. As you can see from the part problems, we have flash, warp, and the part is too big. The standard (quoted) cycle time for this job is 17 seconds. The part tolerance for this job is ± 0.005 .

You will see under the **Cycle Results**, the “Mold Full at VPT” is 9999 and the max pressure alarm came on which means the maximum pressure was used. This means the VPT setting was never reached. You’ll have to correct this. The VPT should occur when the mold is between 94% - 96% full. Because VPT did not occur before the mold was full, the mold flashed and that could cause serious damage to the mold.

Instructions:

1. Log into your Virtual Lab Lessons site (www.paulsonskillbuilder.com)
2. Open lesson “Lab 10”
3. “Cycle” the machine.
4. Begin to make machine control changes and Cycle the machine after each control adjustment to see how your machine control changes have affected your cycle/part.

To complete this lesson:

- Have no part problems or alarms
- Achieve a cycle time of 17 seconds or less

Meet “good molding practices” criteria.

- Cushion size must be less than 10% of the Screw Back Distance.
- Mold Full at VPT must be between 94% - 96%.
- Melt temp must be $\pm 2^{\circ}\text{F}$ of front zone barrel temperature

NOTE: Only make one control change at a time and then click the “Cycle” button to see the effects of that particular control change. This is the best practice to follow when making any control changes whether it be in SimTech or on an actual molding machine. The exceptions are the four barrel temperatures and five fill rates.